






Nº Cil Ø		Junta culata	PVR	Referencia	PVR	Tornillos	
CHEVROLET Gasolina							
SPARK	F8CV	796 68,5 51 98>	3	AD5690	30,47	PA CD5691 134,75 <small>Ø 69,5mm Fibra</small> <small>68 5diam 1,2x1,2x2,5</small> <small>SEG 9-1401-00</small> <small>68,5diam 1,2x1,5x2,8</small> <small>JGO 3 CYL</small> <small>JGO 3 CYL</small>	HBS377
			1			(10) M10 x 1.25 x 97	
MATIZ SPARK	B10S B10S1	995 68,5 67 05>	2	AG7990	24,72	PA CG7990 138,69 <small>Ø 69,5mm Fibra</small>	HBS529
AVEO NUBIRA OPTRA	F14D3	1399 77,9 95 05>	4	Ø80mm AG8000	62,65	PA CG8000 219,34 <small>PA 02-54110-01</small> 	HBS285
			3	61-54115-00	78,29	PA 02-54115-01 219,25 <small>PA 02-54115-01</small> <small>TQ BFS86S</small> <small>77,9 diam 1,2X1,5X2,5</small> <small>7,04</small>	(10) M10 x 1.25 x 166
16 Válvulas							
AVEO	F14D4	1399 77,9 101 08>	4	AH5240	66,96	PA 02-37240-03 215,05 <small>Ø 79,5mm - Fibra</small>	HBS055
	F16D4	1598	4			(10) M10 x 1.25 x 153	
LANOS	A15SMS	1498 76,5 86 05>	4	30-026329-10 BS260	23,26	PA D-32669 96,72 <small>Ø 79,5mm - Fibra</small> <small>TQ BFS63S BL FOL40</small> <small>5,15</small>	HBS002
			5			(10) M10 x 1.25 x 140	

					
	Nº Cil Ø	Junta culata	PVR	Referencia	PVR

CHEVROLET Gasolina

AVEO LANOS 16 Válvulas A16DMS 1598 79 106 97-> 4	7	AB5230 50,16 Ø 80,5mm - Fibra	PA 053313-1000 119,05 TQ BFS86S 7,04 79 diam 1,2x1,5x3	HBS285 (10) M10 x 1.25 x 166
A16DMS 1598 79 106 97-> TACUMA 4		AB5230 50,16 Ø 80,5mm - Fibra	PA 001041199 204,37 TQ BFS86S 7,04 79 diam 1,2x1,5x3	HBS285 (10) M10 x 1.25 x 166
AVEO KALOS 16 Válvulas F16D3 1598 79 107 06-> 4	8	Ø80mm AG8000 62,65 	PA CG8000 219,34 PA 02-54110-01 219,25	HBS285 (10) M10 x 1.25 x 166
		61-54115-00 78,29 	PA 02-54115-01 215,10 TQ BFS86S 7,04 79 diam 1,2x1,5x3	
LACETTI NUBIRA 16 Válvulas Z18XE 1796 80,5 125 07-> 4	10	30-028674-00 AC5460 29,64 Ø 81,5mm Multiláminas	PA 21-28674-20/0 CC5460 108,08	HBS055 (10) M10 x 1.25 x 153
EPICA REZZO - TACUMA 16 Válvulas T20SED 1998 86 133 05-> X20SED 4 X20XEV	11	30-027987-10 BY250 33,03 Ø 87,5mm	PA 21-27987-20/0 DY250 79,05	HBS054 (10) M11 x 1.25 x 105

		Nº Cil Ø	Junta culata	PVR	Referencia	PVR	Tornillos
CHEVROLET Diesel							
DIESEL EPICA CAPTIVA CRUZE 16 Válvulas	Z20S Z20DM Z20S1	1991 83 150 12> 4	AH5690 87,70 Ø 84mm 1,10mm 1 muesca - MLS AH5700 89,87 Ø 84mm 1,20mm 2 muescas - MLS AH5710 87,65 Ø 84mm 1,30mm 3 muescas - MLS	PA CH5690 189,24 Sin Junta de Culata TQ BFS299S 11,27 BL R183S 9,72 BL R218S 17,26 BL R219S 18,59 PUENTES BALANCIN ADM BALANCIN ESC			14-32287-01
		2					
DIESEL GRAND VOYAGER Turbo Diesel	425CLIEE HR425CL	2499 92 114 92>	BK570 34,76 Ø 98mm 1,42mm Sin muescas (x 5) BP260 42,07 Ø 98mm 1,52mm 2 muescas (x 5) BK580 41,00 Ø 98mm 1,62mm 1 muesca (x 5) 30-028472-00 AY400 91,56 Ø 98mm 1,42mm Sin muescas (x 1) 30-028473-00 AY410 91,56 Ø 98mm 1,52mm 2 muescas (x 1) 30-028474-00 AY420 91,56 Ø 98mm 1,62mm 1 muesca (x 1)	PA DK570 57,17 Sin Junta de Culata PA DK573 55,29 Sin Junta de Culata TQ 40432003G * 17,90 BI 10302053F * UNITARIO 12,00 VA 20422014H VARILLA 8,50			HBS108 (10) M 14 x 2 x 137 (4) M 12 x 1.75 x 79.5 (4) M 12 x 1.75 x 115
		1					
DIESEL GRAND VOYAGER VOYAGER Turbo Diesel	2499 92 114 92>	5	30-028536-00 BZ630 125,64 Ø 98mm 1,33mm Sin muescas - MLS 30-028537-00 BZ640 134,03 Ø 98mm 1,43mm 2 muescas - MLS 30-028538-00 BZ650 136,80 Ø 98mm 1,53mm 1 muesca - MLS	PA DZ630 175,07 TQ 40432003G * 17,90 BI 10302053F * UNITARIO 12,00			HBS108 (10) M 14 x 2 x 137 (4) M 12 x 1.75 x 79.5 (4) M 12 x 1.75 x 115
		2					
DIESEL 4 VOYAGER CRDI 16V	2499 92 02>		13002339F * 106,00 1,42MM 1M MLS CON TORNILLOS 13002340F * 106,00 1,52MM 1M MLS CON TORNILLOS	PA 001205104 272,65 TQ R199S 16,84			
		3					