


		Nº Cil	Ø	Junta culata	PVR	Referencia	PVR	Tornillos
DAEWOO Gasolina								
MATIZ TICO	F8C F8CV	796 3	68,5 51 98->	AD5690 Ø 69,5mm Fibra	30,47	PA 001041100 BI 01-4203 STD UNITARIO 68,50diam 1,2x1,5x2,8 SEG JGO 3CYL DIAM68,50 1,2x1,2x2,5	69,70 8,85	HBS377 (10) M10 x 1.25 x 97
				1				
AVEO KALOS 8 Válvulas	F12S3	1150 4	68,5 72 03->	AG7990 Ø 69,5mm Fibra	24,72	PA CG7990	138,69	
				2				
LACETTI NUBIRA 16 Válvulas	F14D3	1399 4	77,9 94 04->	Ø80mm AG8000 	62,65	PA PA 02-54110-01 CG8000	219,34 219,25	HBS285
				3				
				3				
NEXIA ESPERO 8 Válvulas	G15MF	1498 4	76,5 75 95->	30-025706-20 BP800 Ø 80,5mm	23,53	PA 001135005 BI 71-3639/4 STD BA H975/5 STD	66,62 23,50 47,53	HBS002 (10) M10 x 1.25 x 140
				4				

Nº Cil Ø

Junta culata




PVR

Referencia

PVR

Tornillos

DAEWOO Gasolina

<p>NEXIA A15MF 1498 76,5 89 95> ESPERO 4 ARANOS 16 Válvulas</p>	<p>BZ300 36,16 Ø 78mm</p>	<p>PA 02-53300-01 TQ TM3023S BL 125,90 BFS59S 5,51 BI 71-3639/4 STD 4,65</p>	<p>HBS285 (10) M10 x 1.25 x 166</p>
<p>LACETTI F16D3 1598 79 105 03> NUBIRA 4</p>	<p>Ø80mm AG8000 62,65</p>  <p>61-54115-00 78,29</p> 	<p>PA 219,34 PA 02-54110-01 219,25</p> <p>CG8000</p> <p>PA 02-54115-01 TQ BFS86S 215,10 BI 71-3639/4 STD 7,04</p>	<p>HBS285 (10) M10 x 1.25 x 166</p>
<p>LANOS A16DMS 1598 79 106 97> NUBIRA 4 TACUMA 16 Válvulas</p>	<p>AB5230 50,16 Ø 80,5mm - Fibra</p>	<p>PA 053313-1000 119,05</p> <p>PA 001041199 204,37 Para Tacuma TQ BFS86S 7,04 BI 71-3639/4 STD BA 105-20033 23,50 65,00</p>	<p>HBS285 (10) M10 x 1.25 x 166</p>
<p>ARANOS C20LE 1998 86 105 95> ESPERO C20NE 4 LEGANZA NUBIRA 8 Válvulas</p>	<p>30-025819-10 BP820 29,42 Ø 88mm</p> 	<p>PA DP820 59,71</p> <p>TQ TM3023S 5,51</p>	<p>HBS053 (10) M11 x 1.25 x 140</p>
<p>LEGANZA X20SED 1998 86 133 97> NUBIRA T20SED 4 TACUMA Z20L</p>	<p>30-027987-10 BY250 33,03 Ø 87,5mm</p>	<p>PA 21-27987-20/0 DY250 79,05</p> <p>BI 71-3626/4 STD 29,28</p>	<p>HBS054 (10) M11 x 1.25 x 105</p>