

Nº Cil Ø

Junta culata


PVR


Referencia

PVR

Tornillos

CITROEN Gasolina

AX C15 SAXO TU9 TU9M 954 70 60 ⁸⁶ C1A B C3A 4 CDY CDZ	1	BS811 35,33	PA 02-31195-01 59,20	HBS039 (10) M10 x 1.5 X 175
		Ø 74mm 1,30mm	PA Incluye Jta. Culata BS811	
		BR490 45,70	DT012 60,41	
		Ø 74mm 1,50mm 	Sin Junta de Culata BI 01-4123/4 STD H1071/5 23,01	

AX BERLINGO BX / C15 SAXO / ZX Carburador - Inyección	2	AD5701 35,29	PA DT010 94,93	HBS039 (10) M10 x 1.5 X
		Ø 76mm 1,25mm	Incluye Jta. Culata AD5701	
		AD5711 43,35	PA DT012 60,41	
		Ø 76mm 1,50mm	Sin Junta de Culata	
		BS811 35,33	PA 001150003 57,40	
		Ø 74mm 1,30mm TU1M+ BR490 45,70	jg unificado BI 01-4123/4 STD 23,01 BA H1071/5 STD 33,31 AX A203/2 STD 6,74 OP OP283 73,77	
		Ø 74mm 1,50mm TU1M+ 		

Nº Cil Ø

Junta culata

PVR

Referencia

PVR

Tornillos

CITROEN Gasolina

BERLINGO TU1JP 1124 72 60 02 C2 / C3 HFX 4 SAXO HFY <i>Inyección</i> HFZ	AC5701 28,36 Ø 73,5mm 1,26mm - Fibra	PA CC5700 117,96 PA 053673-1051 103,17 BI 01-4163/4 STD 18,68 CON AGUJERO BI 01-4173/4 STD LISO 19,55 BA H1071/5 STD 33,31 AX A203/2 STD 6,74 SEG 08-426300-00 45,56 DIAM72 1,5X1,5X2,5	HBS039 (10) M10 x 1.5 X 175
AX / BX / C15 ZX / C3 TU3M MC 1360 75 67 86> BERLINGO XSARA TU3JP 4 <i>Carburador - Inyección</i> TU3A CPKDX <i>Bloque de Aluminio</i> KDZ K6C K6D KFX KFW	AD5701 35,29 Ø 76mm 1,25mm AD5711 43,35 Ø 76mm 1,50mm	PA DT010 94,93 Incluye Jta. Culata AD5701 PA DT012 60,41 Sin Junta de Culata BI 01-4173/4 STD 19,55 SIN AGUJERO BA H1071/5 STD 33,31 6/2L+2T-4/2R+2T BA H1087/5 STD 31,79 6/2L+2T-4/2R+1T AX A203/2 STD 6,74 75diam 1,75x2x3	HBS039 (10) M10 x 1.5 X 175
AX BX TU3F FM 1360 75 90 89 C15 / ZX TU3FJ2 4 <i>Bloque de Acero</i> KDY KDX K2D K5A	BY130 45,84 Ø 76mm	PA DY130 77,36 Sin Junta de Culata BI 01-4173/4 STD 19,55 SIN AGUJERO BA H1071/5 STD 33,31 6/2L+2T-4/2R+2T BA H1087/5 STD 31,79 6/2L+2T-4/2R+1T AX A203/2 STD 6,74 75diam 1,75x2x3	HBS039 (10) M10 x 1.5 X 175



					
	Nº Cil Ø	Junta culata	PVR	Referencia	PVR

CITROEN Gasolina

SAXO XSARA ZX 8 Válvulas Inyección	TU5JP NFZ NFT NFV	1587 78,5 88 4	93 >	61-28980-00 40,20 Ø 79mm 2+2 muescas - Fibra AY120 32,05 Ø 79mm 3+2 muescas - Fibra	PA Sin Junta de Culata BI 01-4173/4 STD 19,55 SIN AGUJERO BA H1087/5 STD AX A203/2 STD 31,79 78,5diam 1,5x1,5x3	DY130 77,36 HBS039 (10) M10 x 1.5 X 175
SAXO VTS 16 Válvulas	TU5J4 NFX 4	1587 78,5 118 4	96 >	AE5010 69,26 Ø 79,5mm 1,34mm - MLS AE5020 69,26 Ø 79,5mm 1,57mm - MLS AE5030 105,62 Ø 79,5mm 1,77mm - MLS	PA Sin Junta de Culata BI 01-4173/4 STD 19,55 SIN AGUJERO BA H1087/5 STD AX A203/2 STD 31,79 SEG 08-139400-00 6,74 78,5diam 1,2x1,5x2,5	CE5010 181,46 HBS254 (10) M10 x 1.50 x 122
C2 C3 / C4 XSARA 16 Valvulas	TU5JP4 N6ANFU	1587 78,5 90 4	97 >	30-029785-00 AD5180 66,09 Ø 79,5mm 0,62mm - Multiláminas	PA 053674-1000 TQ BFS130S 135,00 BI 01-4173/4 STD 10,41 SIN AGUJERO BA H1087/5 STD AX A203/2 STD 31,79 SEG 08-139400-00 6,74 78,5diam 1,2x1,5x2,5	HBS254 (10) M10 x 1.50 x 122
C3 - C4 DS3 16 Válvulas	EP6 5FW 5F01	1598 77 120 4	07 >	AH6440 73,60 Ø 78mm - 0,9mm - Multiláminas	PA TQ BFS322S TQ 77diam 1,2x1,5x2	CH6440 X8 241,00 LARGO X8 14,98 HBS522 (10) M10 x 1.50 x 122
C4 - C5 DS3 16 Válvulas	EP6DT EP6CDT 5FT 5FV	1598 77 150 4	07 >	AH6730 87,85 Multilaminas - Espesor 0,9mm	PA TQ BFS322S TQ 77diam 1,2x1,5x2	CH6730 X8 222,60 LARGO X8 14,98 HBS522 (10) M10 x 1.50 x 122

					
	Nº Cil Ø	Junta culata	PVR	Referencia	PVR

CITROEN Gasolina

C5 XSARA 16 Válvulas	EW7J4 6FZ	1749 82,7 115 4	00 >	AD5310 90,87 Ø 83mm 0,75mm - MLS	PA BI 01-4155/4 STD	CD5310 183,03 30,57	HBS259 (10) M11 x 1.5 x 144.5	17
XANTIA XSARA ZX 16 Válvulas	XU7JP4 LFY	1761 83 115 4	95 >	AD5100 39,95 Ø 84mm - Fibra	PA BI 01-4155/4 STD BA H1074/5 STD AX A214/4 STD SEG 08-323400-00 83diam 1,5x1,5x3	CD5100 173,35 30,57 50,02 12,62 55,10	HBS089 (10) M11 x 1.5 x 159	18
BX ZX Inyección 8 Válvulas	XU9JA J1 XU9J2 JAZ XU9M D6A B D E DFV Y Z DDZ DKZ DZF	1905 83 102 4	86 >	BL650 27,41 Ø 84mm 1,20mm - Fibra BR510 41,20 Ø 84mm 1,44mm - Fibra	PA 21-25204-21/0 Sin Junta de Culata BI 71-3628/4 STD BA H1074/5 STD AX A214/4 STD SEG 08-322400-00 83diam 1,5x1,5x3	DN590 97,09 35,56 50,02 12,62 34,17	HBS038 HBS083 (10) M11 x 1.5 x	19
C4 / C5 / C8 EVASION JUMPY / XSARA 16 Válvulas	EW10A EW10J4 S RFK RFN RLZ	1998 85 136 4 6FZ	00 >	AD5300 69,26 Ø 86mm - MLS	PA BI 01-4155/4 STD BA 85diam 1,2x1,5x2,5	CD5300 180,35 30,57 11,50	HBS259 (10) M11 x 1.5 x 144.5	21

Nº Cil Ø

Junta culata

PVR

Referencia

PVR

Tornillos

CITROEN Diesel

<p>DIESEL C1 C2 C3 8 Válvulas Turbo Intercooled Inyección Directa</p> <p>DV4TD 1398 73,7 70 02 DV4D 4 > 8HX 8HZ 8HT 8HS</p>	<p>61-35430-00 81,82 Ø 76mm 1,25mm - 2+2 muescas - MLS</p> <p>61-35430-10 81,82 Ø 76mm 1,30mm - 3+2 muescas - MLS</p> <p>61-35430-20 81,82 Ø 76mm 1,35mm - 1+2 muesca - MLS</p> <p>61-35430-30 81,82 Ø 76mm 1,40mm - 4+2 muescas - MLS</p> <p>61-35430-40 81,82 Ø 76mm 1,45mm - 5+2 muescas - MLS</p>	<p>PA CD513 113,07 Sin Junta de Culata</p> <p>PB 083678-1051 136,00 AL CAM726 83,73 TQ BFS156S 5,57</p> <p>Bola 7,9mm</p> <p>BL R173S UNITARIO 6,71 BI 71-3986 STD BA 32,64 H1066/5 STD AX 54,23 A217/2 STD SEG 8,94 800046010000 35,87 73,71 diam 2,5x1,95x2,5</p>	<p>HBS359 (10) M11 x 1.5 x 150</p>
<p>DIESEL C3 C2 HDI 16 Válvulas Turbo Intercooled Inyección Directa</p> <p>DV4TED4 1398 73,7 68 02 8HY 4 ></p>	<p>61-37350-00 94,06 Ø 74,7mm 1,25mm - MLS</p> <p>61-37350-10 94,06 Ø 74,7mm 1,30mm - MLS</p> <p>61-37350-20 94,06 Ø 74,7mm 1,35mm - MLS</p> <p>61-37350-30 94,06 Ø 74,7mm 1,40mm - MLS</p> <p>61-37350-40 94,06 Ø 74,7mm 1,45mm - MLS</p>	<p>PA 043688-1000 82,00 Sin Junta de Culata</p> <p>TQ BFS148S 5,29</p> <p>Bola 8,4mm</p> <p>BL R174S UNITARIO 7,71 BI 71-3986 STD BA 32,64 H1066/5 STD AX 54,23 A217/2 STD SEG 8,94 800046010000 35,87 73,71 diam 2,5x1,95x2,5</p>	<p>HBS359 (10) M11 x 1.5 x 150</p>
<p>DIESEL AX SAXO / XSARA ZX</p> <p>TUD5 1527 77 54 91 VJYVJZ 4 ></p>	<p>BY150 73,52 Ø 78mm 1,75mm - Fibra</p> <p>61-33645-00 71,26 Ø 78,2mm 1,6mm - MLS</p>	<p>PA 21-28757-20/0 DY15 121,28 Sin Junta de Culata</p> <p>TQ FOL126 4,86 BI 01-4362/4 STD BA H1087/5 27,63 77diam 2x1,75x3</p>	<p>HBS113 (10) M11 x 1.50 X 185</p>

Nº Cil Ø

Junta culata

PVR

Referencia

PVR

Tornillos

CITROEN Diesel

DIESEL BERLINGO JUMPY XSARA DW8 DW8B WJX WJY WJZ	1868 82,2 69 ⁹⁸ 4 >	61-33720-00 Ø 84mm 1,26mm 1+2 muescas - MLS	62,93	PA 21-29482-20/0 CA5830 Sin Junta de Culata	86,11	HBS245 (10) M12 x 1.5 x 125 HBS084 (10) M12 x 1.5 x 120
		61-33720-10 Ø 84mm 1,30mm 2+2 muescas - MLS	62,93	PA 043670-1000 Sin Junta de Culata	43,39	
		61-33720-20 Ø 84mm 1,34mm 3+2 muescas - MLS	62,93	AL CAM373 BI 01-4200/4 STD BA H1057/5	70,91 30,09	
		61-33720-30 Ø 84mm 1,38mm 4+2 muescas - MLS	62,93	STD AX A160/4 STD ^{SEG} 08-104000-00	25,97 7,56 34,55	
		61-33720-40 Ø 84mm 1,42mm 5+2 muescas - MLS	62,93	82,20diam 2x2x3		
		61-33720-50 Ø 84mm 1,46mm - MLS Junta Sin Cordón de Silicona	62,93			

8

DIESEL BERLINGO BX C25 JUMPER JUMPY XANTIA XSARA ZX XUD9 162 DJY DJZ D9A D9B	1905 83 64 ⁸³ 4 >	30-028475-00 BX880 Ø 84mm 1,36mm 1 muesca - Fibra	78,78	PA DJ720 Sin Junta de Culata Juego Unificado	53,40	HBS084 (10) M12 x 1.5 x 120
		30-028476-00 BX890 Ø 84mm 1,40mm 2 muescas - Fibra	64,40	AL CAM373 BI 01-4200/4 STD BA H1057/5	70,91 30,09	
		30-028477-00 BX900 Ø 84mm 1,44mm 3 muescas - Fibra	64,19		STD AX A214/4 STD ^{SEG} 08-152000-00	
		30-028478-00 BX910 Ø 84mm 1,48mm 4 muescas - Fibra	63,34	83diam 2x2x3		
		30-028479-00 BX920 Ø 84mm 1,52mm 5 muescas - Fibra	64,25		OP OP171	

9

Nº Cil Ø

Junta culata

PVR

Referencia

PVR

Tornillos

CITROEN Diesel

<p>DIESEL EVASION XUD9TE 1905 83 92 92 JUMPER JUMPY TF UTF BTF 4 XANTIA XSARA ZX D8A D8B <i>Turbo Diesel</i> D8C DHX DHY</p>	<p>61-33155-00 66,76 Ø 84mm 1,36mm 3+1 muesca - MLS 61-33155-10 66,76 Ø 84mm 1,40mm 3+2 muescas - MLS 61-33155-20 66,76 Ø 84mm 1,44mm 3+3 muescas - MLS 61-33155-30 66,76 Ø 84mm 1,48mm 3+4 muescas - MLS 61-33155-40 66,76 Ø 84mm 1,52mm 3+5 muescas - MLS 61-33155-50 66,76 Ø 84mm 1,59mm 3+0 muescas - MLS</p>	<p>PA DJ720 53,40 Sin Junta de Culata Juego Unificado AL CAM373 70,91 BI 71-3730/4 STD 35,96 UÑETA EN LA PUNTA BI 71-3899/4 STD 33,88 UÑETA A 2MM DE LA PUNTA BA H1057/5 STD AX A188/4 STD 25,97 SEG 08-105500-00 12,04 60,26 83diam 3x2x3 OP OP217 66,00</p>	<p>HBS277 (10) M12 x 1.5 x 148</p>
<p>DIESEL BERLINGO DW10TD 1997 85 110 98 C5 EVASION JUMPER DW10ATED 4 JUMPY XANTIA DW10BTED RHV XSARA HDI RHX RHY RHZ <i>8 Válvulas</i></p>	<p>30-029477-00 AC5011 58,00 Ø 86mm 1,30mm 1 muesca - MLS 30-029478-00 AC5020 63,49 Ø 86mm 1,35mm 2 muescas - MLS 103671-5253 55,56 Ø 86mm 1,40mm 3 muescas - MLS 30-029480-00 AC5040 64,21 Ø 86mm 1,45mm 4 muescas - MLS 30-029481-00 AC5051 CONSULTAR Ø 86mm 1,50mm 5 muescas - MLS</p>	<p>PA 043671-1000 63,49 Sin Junta de Culata AL CAM679 TQ BFS148SBL R364S 93,41 5,29 BI 71-3952/4 STD BA H1057/5 STD AX A214/4 STD 6,43 131,00 SEG 800071410000 25,97 12,62 34,57 85diam 3,5x2x3</p>	<p>HBS261 (10) M12 x 1.5 x 126</p>
<p>DIESEL C5 DW10ATED4 1997 85 109 01 C8 EVASION JUMPER RHM 4 JUMPY HDI <i>16 Válvulas</i></p>	<p>61-34370-00 50,00 Ø 86mm 1,25mm 1 muesca - MLS 61-34370-10 50,00 Ø 86mm 1,30mm 2 muescas - MLS 61-34370-20 50,00 Ø 86mm 1,35mm 3 muescas - MLS 61-34370-30 50,00 Ø 86mm 1,40mm 4 muescas - MLS</p>	<p>PA 02-34404-01 89,35 Sin Junta de Culata TQ BFS156SBL R360S 5,57 BI 71-3952/4 STD BA H1057/5 STD AX A214/4 STD 6,71 131,00 SEG 800071410000 25,97 12,62 85diam 3,5x2x3</p>	<p>HBS261 (10) M12 x 1.5 x 126</p>

Nº Cil Ø

Junta culata

PVR

Referencia

PVR

Tornillos

CITROEN Diesel

<p>DIESEL C4 C5 C8 HDI 16 Válvulas Inyección Directa</p> <p>DW10BTED4 1997 85 136 04 RHJ 4 RHK RHR</p>	<p>61-34370-00 50,00 Ø 86mm 1,25mm 1 muesca - MLS</p> <p>61-34370-10 50,00 Ø 86mm 1,30mm 2 muescas - MLS</p> <p>61-34370-20 50,00 Ø 86mm 1,35mm 3 muescas - MLS</p> <p>61-34370-30 50,00 Ø 86mm 1,40mm 4 muescas - MLS</p>	<p>PA 043690-1099 82,01 Sin Junta de Culata</p> <p>AL C332 AL ADMISION 121,98 CAM749 ESCAPE 125,98</p> <p>TQ BFS156S BL 5,57 R360S 6,71</p> <p>BI 71-3952/4 STD BA 131,00 H1057/5 STD AX 25,97 A214/4 STD 12,62</p> <p>85diam 3,5x2x3</p>	<p>HBS261 (10) M12 x 1.5 x 126</p>
<p>DIESEL JUMPER HDI - 16 Válvulas</p> <p>P22DTE 2198 86 120 06 4HU 4 4HV</p>	<p>61-37365-00 80,13 Ø 87mm 1,10mm 1 muesca</p> <p>61-37365-10 80,13 Ø 87mm 1,15mm 2 muescas</p> <p>61-37365-20 80,13 Ø 87mm 1,20mm 2 muescas</p>	<p>PA CH6390 166,91 Sin Junta de Culata</p> <p>PB 081519-1000 119,00</p> <p>AL C340 ADMISION 171,20 AL C341 ESCAPE 171,20</p> <p>TQ FOL251 7,45</p> <p>BL BFS320S 10,41 BI 71-4066/4 STD 47,51 BA H1018/5 STD 80,38 SEG 08-427700-00 69,91</p> <p>86diam 2x2x2</p>	<p>14-32341-01</p>
<p>DIESEL JUMPER HDI 8 Válvulas</p> <p>DW12TED 2179 85 101 02 4HY 4</p>	<p>61-33875-00 76,33 Ø 86mm 1,25mm 1+2 muescas - MLS</p> <p>61-33875-10 76,33 Ø 86mm 1,30mm 2+2 muescas - MLS</p> <p>61-33875-20 76,33 Ø 86mm 1,35mm 3+2 muescas - MLS</p> <p>61-33875-30 65,37 Ø 86mm 1,40mm 4+2 muescas - MLS</p>	<p>PA 21-29484-20/0 CC5010 96,35 Sin Junta de Culata</p> <p>AL CAM679 93,41 TQ BFS148S 5,29</p> <p>Bola 8,4mm</p> <p>BL R364S 6,43 BI 71-3952/4 STD BA H1057/5 131,00 STD AX A214/4 STD SEG 25,97 800071410000 12,62</p> <p>85diam 3,5x2x3</p>	<p>HBS261 (10) M12 x 1.5 x 126</p>

Nº Cil Ø

Junta culata

PVR

Referencia

PVR

Tornillos

CITROEN Diesel

<p>DIESEL C5 C8 HDI 16 Válvulas</p> <p>DW12TED4 2179 85 133 01 4HX 4 4HW</p>	<p>61-34370-00 50,00 Ø 86mm 1,25mm 1 muesca - MLS</p> <p>61-34370-10 50,00 Ø 86mm 1,30mm 2 muescas - MLS</p> <p>61-34370-20 50,00 Ø 86mm 1,35mm 3 muescas - MLS</p> <p>61-34370-30 50,00 Ø 86mm 1,40mm 4 muescas - MLS</p>	<p>PA CD5490 114,36 Sin Junta de Culata</p> <p>AL CAM750 ADMISION 108,87 AL CAM751 ESCAPE 101,17</p> <p>TQ BFS156S 5,57 Bola 7,9mm</p> <p>BL R360S 6,71 BI 71-3952/4 STD BA H1057/5 131,00 85diam 3,5x2x3</p>	<p>HBS261 (10) M12 x 1.5 x 126</p>
<p>DIESEL JUMPER XM 12 Válvulas Atmosférico y Turbo</p> <p>DJ5 2446 92 103 DJ5T 4 DK5ATE T8A THZ T9A</p>	<p>BY140 50,22 Ø 93mm Fibra</p>	<p>PA DY140 119,83 Sin Junta de Culata</p> <p>AL CAM677 186,02 TQ FOL109 16,00 BL BFS150S 6,60 BI 71-3781/4 STD 41,99 BA CONSULTAR COSULTAR 48,23 SEG 08-112400-00 DIAM81 2,25X2X2</p>	<p>HBS114 (14) M12 x 1.5 x (8) M10 x 1.5 x</p>
<p>DIESEL JUMPER TDI 8 Válvulas</p> <p>DJ5TED 2446 92 107 96 THX 4</p>	<p>AE5050 116,80 Ø 93mm Multiáminas</p>	<p>PA CE5050 178,90 Incluye Junta de Culata</p> <p>AL CAM678 185,50 TQ FOL118 7,52 BI 71-3951/4 STD 168,31 BA CONSULTAR COSULTAR 38,48 SEG 08-135800-00 DIAM81 3,50X2X3,50</p>	<p>HBS273 (10) M12 x 1.5 x (8) M10 x 1.5 x</p>



Nº Cil Ø

Junta culata

PVR

Referencia

PVR

Tornillos

CITROEN Diesel

DIESEL DT17TED4 2720 81 200 07>
C5 UHZ 6
C6
HDI
V6 - 24 Válvulas

23

Ø82,5mm 1,17mm - 2 Muestras - MLS
AH5730 69,84

Ø82,5mm 1,22mm - 3 Muestras - MLS
AH5731 69,84

Ø82,5mm 1,27mm - 4 Muestras - MLS
AH5732 69,84

Ø82,5mm 1,32mm - 5 Muestras - MLS
AH5733 69,84

PA

Sin Junta de Culata
CH5730 271,61